




- 2 Sharpe Health School
- 3 Theodore Roosevelt High School
- 4 MacFarland Middle School
- 5 Upshur Dog Park
- 6 Upshur Recreation Center
- Upshur Community Garden
- 8 Upshur Park
- 9 Roosevelt Gym / Pool
- 10 Petworth Library
- 11 Petworth Recreation Center
- 12 Georgia Ave-Petworth Metro Stop
- Raymond Recreation Center and Playground
- Barnard Elementary School
- 15 Piney Branch Park
- Powell Elementary School
- 17 EL Haynes Public Charter School
- 18 Center City Public Charter School
- 19 Petworth Elementary School
- 20 Raymond Education Campus













**Existing Aerial View Looking Northwest EXISTING CONDITIONS** 







- Washington Health School | Annex Building 1Story Brick Building with Basement
- Parking
- Parking / Service
- Playground
- Heritage Tree
- Retaining Walls





1 Western Side of Dorothy Height Elementary School (Vocational School)



2 Looking East Towards Theodore Roosevelt High School




3 Roosevelt High School



4 Corner of Allison Street and 13th Street Looking Northeast



5 Corner of Allison Street and 13th Street Looking Northwest



Key Plan







1 South Side (Vocational School)







Key Plan

2 Southwest Side (Vocational School)

4 Northeast Side (Vocational School)

EXISTING CONDITIONS Vocational School | **Existing Conditions Photos** 



1 East Side (Washington Health School)



2 West Side (Washington Health School)




3 Courtyard (Washington Health School)




4 North Side (Washington Health School)



5 South Side (Washington Health School)



Key Plan









- Historic Porch
- Administration
- Welcome Desk
- Circulation
- Stage
- Egress Stair
- Areaway
- Cafeteria
- Accessible Entrance
- Kitchen
- Shed
- Mechanical Units
- Historical Closet
- Historical Entrance
- Classroom
- Courtyard
















- Locker Room
- Elevator
- Main Mechanical Room
- Areaway
- Unfinished Basement
- Pipe Tunnel
- Circulation
- Crawlspace






**VOCATIONAL SCHOOL** 

- 1 Open to Gym Below
- 2 Classroom
- 3 Circulation
- 4 Egress Stairs
- 5 Parapet
- 6 Low Slope Membrane Roof
- 7 Brick Chimney
- 8 Skylights






EXISTING CONDITIONS Existing Second Floor Plan


ck architects


June 2, 2022
spack architects 2022



**VOCATIONAL SCHOOL** 

- 1 Roof Below
- 2 Classroom
- 3 Circulation
- 4 Egress Stairs
- 5 Brick Chimney
- 6 Skylight
- Low Slope Membrane Roof
- 8 Parapet






EXISTING CONDITIONS Existing Third Floor Plan


ck architects


June 2, 2022
spack architects 2022





- 2 Skylight
- 3 Low Slope Membrane Roof
- 4 Brick Chimney
- 5 Parapet
- 6 Clay Roof







EXISTING CONDITIONS Existing Roof Plan

cox graae + spack architects

June 2, 2022

copyright © cox graae + spack architects 2022





### **EXISTING ELEVATION NOTES**

1	Decorative Brick Attic Vent	12	Brick Belt Course
2	Decorative Metal Railings, Painted	13	Brick Cheek Walls at Courtyard Stairs
3	Ornamental Metal Cornice	14	Limestone Chimney Cap
4	Painted Ornamental Metal Cornice	15	Limestone Cornice
5	Historic Main Entrance	16	Limestone Coping
6	Historic Building Signage	17	Limestone Steps
7	Historical Flagpole	18	Hard Limestone Watertable
8	Historic Concrete Steps	19	Concrete ADA Site Ramp and Steps
9	Replacement Vinyl Windows	20	ADA Ramp
10	Fabric Awning	21	Galvanized Metal Railing
11	Brick Chimney	22	Galvanized Metal Mechanical Equipment Support Frame

Mechanical Equipment

24 Mechanical Duct

25 Metal Infill Panel at Former Fan Coil Unit Opening

26 Prefinished Metal Coping

27 Wood and Metal Portico Entrance, Painted

28 Clay Tile


23


29

Site Wall

**EXISTING CONDITIONS** Washington HS + Vocational School | Existing East Elevation








#### **EXISTING ELEVATION NOTES**


1	Decorative Brick Attic Vent	12	Bri
2	Decorative Metal Railings, Painted	13	Bri
3	Ornamental Metal Cornice	14	Lin
4	Painted Ornamental Metal Cornice	15	Lin
5	Historic Main Entrance	16	Lin
6	Historic Building Signage	17	Lin
7	Historical Flagpole	18	На
8	Historic Concrete Steps	19	Со
9	Replacement Vinyl Windows	20	AD
10	Fabric Awning	21	Ga
11	Brick Chimney	22	Ga Fra

12	Brick Belt Course	23	Mechanical Equipment	
13	Brick Cheek Walls at Courtyard Stairs	24	Mechanical Duct	
14	Limestone Chimney Cap	25	Metal Infill Panel at Former Fan Coil Unit Openir	ng
15	Limestone Cornice	26	Prefinished Metal Coping	
16	Limestone Coping	27	Wood and Metal Portico Entrance, Painted	
17	Limestone Steps	28	Clay Tile	
18	Hard Limestone Watertable	29	Site Wall	
19	Concrete ADA Site Ramp and Steps			
20	ADA Ramp			
21	Galvanized Metal Railing			
22	Galvanized Metal Mechanical Equipment Support Frame			2:1

EXISTING CONDITIONS Vocational School | Existing North Elevation








### **EXISTING ELEVATION NOTES**


1	Decorative Brick Attic Vent
2	Decorative Metal Railings, Painted
3	Ornamental Metal Cornice
4	Painted Ornamental Metal Cornice
5	Historic Main Entrance
6	Historic Building Signage
7	Historical Flagpole
8	Historic Concrete Steps
9	Replacement Vinyl Windows
10	Fabric Awning
11	Brick Chimney

12	Brick Belt Course	23	Mechanical Equipment
13	Brick Cheek Walls at Courtyard Stairs	24	Mechanical Duct
14	Limestone Chimney Cap	25	Metal Infill Panel at Former Fan Coil Unit Opening
15	Limestone Cornice	26	Prefinished Metal Coping
16	Limestone Coping	27	Wood and Metal Portico Entrance, Painted
17	Limestone Steps	28	Clay Tile
18	Hard Limestone Watertable	29	Site Wall
19	Concrete ADA Site Ramp and Steps		
20	ADA Ramp		
21	Galvanized Metal Railing		
22	Galvanized Metal Mechanical Equipment Support Frame		2

EXISTING CONDITIONS Vocational School | Existing South Elevation







### **EXISTING ELEVATION NOTES**

1	Decorative Brick Attic Vent	12	Brick Belt Course
2	Decorative Metal Railings, Painted	13	Brick Cheek Walls at Courtyard Stairs
3	Ornamental Metal Cornice	14	Limestone Chimney Cap
4	Painted Ornamental Metal Cornice	15	Limestone Cornice
5	Historic Main Entrance	16	Limestone Coping
6	Historic Building Signage	17	Limestone Steps
7	Historical Flagpole	18	Hard Limestone Watertable
8	Historic Concrete Steps	19	Concrete ADA Site Ramp and Steps
9	Replacement Vinyl Windows	20	ADA Ramp
10	Fabric Awning	21	Galvanized Metal Railing
11	Brick Chimney	22	Galvanized Metal Mechanical Equipment Support Frame

Mechanical Equipment

24 Mechanical Duct

25 Metal Infill Panel at Former Fan Coil Unit Opening

26 Prefinished Metal Coping

27 Wood and Metal Portico Entrance, Painted


23


29

28 Clay Tile

Site Wall







### **EXISTING ELEVATION NOTES**

1	Decorative Brick Attic Vent	12	Brick Belt Course
2	Decorative Metal Railings, Painted	13	Brick Cheek Walls at Courtyard Stairs
3	Ornamental Metal Cornice	14	Limestone Chimney Cap
4	Painted Ornamental Metal Cornice	15	Limestone Cornice
5	Historic Main Entrance	16	Limestone Coping
6	Historic Building Signage	17	Limestone Steps
7	Historical Flagpole	18	Hard Limestone Watertable
8	Historic Concrete Steps	19	Concrete ADA Site Ramp and Steps
9	Replacement Vinyl Windows	20	ADA Ramp
10	Fabric Awning	21	Galvanized Metal Railing
11	Brick Chimney	22	Galvanized Metal Mechanical Equipment Support Frame

Mechanical Equipment

24 Mechanical Duct

25 Metal Infill Panel at Former Fan Coil Unit Opening

Prefinished Metal Coping

27 Wood and Metal Portico Entrance, Painted

28 Clay Tile


23


26

29

Site Wall

**EXISTING CONDITIONS** Washington Health School | Existing South Elevation cox graae + spack architects June 2, 2022 copyright © cox graae + spack architects 2022





### **EXISTING ELEVATION NOTES**

1	Decorative Brick Attic Vent	12	Brick Belt Course	23	Mechanical Equipment	
2	Decorative Metal Railings, Painted	13	Brick Cheek Walls at Courtyard Stairs	24	Mechanical Duct	
3	Ornamental Metal Cornice	14	Limestone Chimney Cap	25	Metal Infill Panel at Former Fan Coil Unit Openi	ing
4	Painted Ornamental Metal Cornice	15	Limestone Cornice	26	Prefinished Metal Coping	
5	Historic Main Entrance	16	Limestone Coping	27	Wood and Metal Portico Entrance, Painted	
6	Historic Building Signage	17	Limestone Steps	28	Clay Tile	
7	Historical Flagpole	18	Hard Limestone Watertable	29	Site Wall	
8	Historic Concrete Steps	19	Concrete ADA Site Ramp and Steps			
9	Replacement Vinyl Windows	20	ADA Ramp			
10	Fabric Awning	21	Galvanized Metal Railing			
11	Brick Chimney	22	Galvanized Metal Mechanical Equipment Support Frame			2:17

**EXISTING CONDITIONS** Washington Health School | **Existing North Elevation** 




2:17


cox graae + spack architects June 2, 2022

- 01 New Addition to connect the Existing Buildings
- 02 Maximize outdoor learning and play
- O3 Building to celebrate and be an incubator for transformation & change

### **New Addition to connect the Existing Buildings**




FIRST FLOOR



**SECOND FLOOR** 


### Maximizing outdoor learning and play spaces 02



### Building to celebrate and be an incubator for transformation & change








**Dorothy I Height**(1912-2010)
Civil Rights and Women's Rights Activist

· Celebrate life and legacy through public art commissions

### 03 Building to celebrate and be an incubator for transformation & change

**Create Connections to Nature: Incorporating Biophilic Design Principals** 


Biophilic design seeks to connect our inherent need to affiliate with nature in the modern built environment















- Washington Health School | Annex Building 1 Story Brick Building with Basement
- 3 2 Story Addition
- 4 Parking
- 5 Service
- 6 Outdoor Classroom Synthetic Turf
- 7 Terraced Seating
- 8 Outdoor Dining / Multi-Purpose Space
- 9 Rubberized Surfacing Courtyard
- 10 Historic Courtyard
- 11 Early Childhood Development Playground
- 12 Entry Plaza
- 13 5-12 Year Playground and Traffic Garden
- 14 Secondary Drop Off
- 15 Slope Stabilization
- 16 Heritage Tree to Remain
- 17 Existing Tree to Remain
- 18 Street Trees to Remain













Cafeteria

Entrance Lobby

Administration

Classroom

Gymnasium

Restored Historic Stage

Entry Plaza


Dining Terrace

Health Suite

Student Support Space

Historic Courtyard Play Space

Historic Front Porch







15 MEP Support Space

16 Custodial Space

Teacher Collaboration Space

18 Food Service Spaces


19 Crawl Space


20 Service Yard

21 Library Terrace

22 Light Well

23 Unfinished Basement











- 16 Custodial Space
- 17 Teacher Collaboration Space
- 24 Small Group Instruction Space
- 27 Skylight










- 16 Custodial Space
- 25 Outdoor Classroom
- 26 Roof Terrace
- 27 Skylight
- 28 Greenroof
- 29 Roof Below
















CONCEPT DESIGN Proposed Roof Plan





### PROPOSED ELEVATION NOTES


1	Existing Vinyl Windows to Remain
2	Existing Masonry Restored as Required
3	Aluminum Clad Replica Door
4	Architectural Aluminum Mechanical Louver
5	Aluminum Curtainwall System
6	Pre-Finished Aluminum Trim
7	Modular Slate Veneer
8	Pre-Finished Aluminum Panel - Accent Color
9	Pre-Finished Aluminum Sun Control Fin
10	Replica Aluminum High Performance Window
11	Restored Tin Cornice

2	Restored Wood and Tin Portico
3	Terracotta Rainscreen System
4	Pre-Finished Perforated Aluminum Panel
5	Pre-Finished Aluminum Panel at Canopy
6	Exposed Steel, Painted
7	Pre-Finished Aluminum Panel
8	Limestone Veneer
9	Skylight
20	Synthetic Slate Roof
21	Replica Metal Railing, Painted
22	New Brick to Match Existing

23	Replica Historic Signage
24	New Window Well to Lower Level
25	Restored Stone Porches
26	Replica Concrete Steps
27	42" Tall Pre-Finished Aluminum Fence
28	Brick Cheekwall with Cast Stone Cap
29	Galvanized Steel Bridge with Galvanized Stee Guardrail
30	Restored Historic Flagpole
31	Parking and Service Yard

CONCEPT DESIGN Proposed East Elevation





Above & Left
Terracotta Rainscreen System


- + Nominal 1'x3' Panels
- + 4 Colors
- + Random Pattern



Above
Limestone Cladding
Location: Egress Stair / Elevator Exterior Walls



Above **DARK BRICK Location:** Addition First Floor



Perforated Metal Panel
Location: Roof Terrace / Outdoor Classroom
+ Custom Graphics (Public Art Program)



Above Modular Skylight
Location: Commons / South Side of Addition / Egress Stairs



Right

Perforated Metal Panel

Location: Roof Terrace /

Outdoor Classroom

+ Custom Graphics

(Public Art Program)



Unit Pavers

Location: Entrance Terrace / Dining and Library Terrace


+ Size 6"x24" and 3No. Colors Running Bond,. Random Patter


2.1

Above











### PROPOSED ELEVATION NOTES

1	Existing Vinyl Windows to Remain	12	Restored Wood and Tin Portico	23	Replica Historic Signage
2	Existing Masonry Restored as Required	13	Terracotta Rainscreen System	24	New Window Well to Lower Level
3	Aluminum Clad Replica Door	14	Pre-Finished Perforated Aluminum Panel	25	Restored Stone Porches
4	Architectural Aluminum Mechanical Louver	15	Pre-Finished Aluminum Panel at Canopy	26	Replica Concrete Steps
5	Aluminum Curtainwall System	16	Exposed Steel, Painted	27	42" Tall Pre-Finished Aluminum Fence
6	Pre-Finished Aluminum Trim	17	Pre-Finished Aluminum Panel	28	Brick Cheekwall with Cast Stone Cap
7	Modular Slate Veneer	18	Limestone Veneer	29	Galvanized Steel Bridge with Galvanized Steel
8	Pre-Finished Aluminum Panel - Accent Color	19	Skylight		Guardrail
9	Pre-Finished Aluminum Sun Control Fin	20	Synthetic Slate Roof	30	Restored Historic Flagpole
10	Replica Aluminum High Performance Window	21	Replica Metal Railing, Painted	31	Parking and Service Yard
11	Restored Tin Cornice	22	New Brick to Match Existing		

CONCEPT DESIGN Proposed North Elevation






### PROPOSED ELEVATION NOTES


1	Existing Vinyl Windows to Remain
2	Existing Masonry Restored as Required
3	Aluminum Clad Replica Door
4	Architectural Aluminum Mechanical Louver
5	Aluminum Curtainwall System
6	Pre-Finished Aluminum Trim
7	Modular Slate Veneer
8	Pre-Finished Aluminum Panel - Accent Color
9	Pre-Finished Aluminum Sun Control Fin
10	Replica Aluminum High Performance Window
11	Restored Tin Cornice

2	Restored Wood and Tin Portico
3	Terracotta Rainscreen System
4	Pre-Finished Perforated Aluminum Panel
5	Pre-Finished Aluminum Panel at Canopy
5	Exposed Steel, Painted
7	Pre-Finished Aluminum Panel
3	Limestone Veneer
9	Skylight
0	Synthetic Slate Roof
1	Replica Metal Railing, Painted
2	New Brick to Match Existing

23	Replica Historic Signage
24	New Window Well to Lower Level
25	Restored Stone Porches
26	Replica Concrete Steps
27	42" Tall Pre-Finished Aluminum Fence
28	Brick Cheekwall with Cast Stone Cap
29	Galvanized Steel Bridge with Galvanized Stee Guardrail
30	Restored Historic Flagpole
31	Parking and Service Yard

CONCEPT DESIGN Proposed West Elevation







### PROPOSED ELEVATION NOTES

1	Existing Vinyl Windows to Remain	12	Restored Wood and Tin Portico	23	Replica Historic Signage
2	Existing Masonry Restored as Required	13	Terracotta Rainscreen System	24	New Window Well to Lower Level
3	Aluminum Clad Replica Door	14	Pre-Finished Perforated Aluminum Panel	25	Restored Stone Porches
4	Architectural Aluminum Mechanical Louver	15	Pre-Finished Aluminum Panel at Canopy	26	Replica Concrete Steps
5	Aluminum Curtainwall System	16	Exposed Steel, Painted	27	42" Tall Pre-Finished Aluminum Fence
6	Pre-Finished Aluminum Trim	17	Pre-Finished Aluminum Panel	28	Brick Cheekwall with Cast Stone Cap
7	Modular Slate Veneer	18	Limestone Veneer	29	Galvanized Steel Bridge with Galvanized Steel
8	Pre-Finished Aluminum Panel - Accent Color	19	Skylight	Guardraii	
9	Pre-Finished Aluminum Sun Control Fin	20	Synthetic Slate Roof	30	Restored Historic Flagpole
10	Replica Aluminum High Performance Window	21	Replica Metal Railing, Painted	31	Parking and Service Yard
11	Restored Tin Cornice	22	New Brick to Match Existing		

CONCEPT DESIGN Proposed South Elevation







### PROPOSED SECTION NOTES


1	Cafeteria
	atereria

- 2 Ramp / Stair Connection to Annex
- Service / MEP Tunnel
- 4 Roof Top Terrace / Outdoor Classroom
- 5 Concrete Low Wall
- 6 Slate Veneer Modular
- 7 Steel Structure, Painted
- 8 Terracotta Rainscreen System
- 9 Pre-Finished Aluminum Trim
- 10 Aluminum Curtainwall / Storefront
- 11 Drywall With Reveals, Painted

- Perforated Aluminum Panel with Public Art Custom Graphics
  - Pre-Finished Aluminum Panels
- Pre-Finished Aluminum Panels at Canopy
  - Perimeter
- 15 Synthetic Wood Effect Soffit
- 16 Skylight

13

CONCEPT DESIGN Proposed South Addition Section





### PROPOSED SECTION NOTES

Discovery	Commons
Discovery	COMMINIONS


- Service / MEP Tunnel
- 3 Pre-Finished Aluminum Panels
- 4 Hollow Metal Door, Painted
- 5 Aluminum Curtainwall
- 6 Decorative Brick, Restored as Required
- 7 Limestone Veneer
- 8 Existing Brick, Restored as Required
- 9 Concrete Seatwall / Planter Wall
- 10 Fabric Wrapped Acoustic Panels
- 11 Architectural Louver Fur MEP System


- Replacement Aluminum Window
- 13 Steel Framed Open Stair
- 14 Skylight

12

- 15 Synthetic Slate Roof
- 5 Tree

CONCEPT DESIGN Proposed South Burdick Section





### PROPOSED SECTION NOTES

Replica Concrete Steps
------------------------

- 2 Early Childhood Play Courtyard
- Restored Historical Flagpole
- 4 Existing Skylight
- 5 New Skylight
- 6 Limestone Veneer
- 7 Decorative Plaster with Thermal Graphics
- 8 Discovery Commons
- 9 Cafeteria
- 10 Food Service Area
- 11 Servery

- 12 Classroom
- 13 Main MEP Room
- 14 Restored Historic Porches
- 15 Attic
- 16 Rooftop Terrace / Outdoor Classroom
- 17 Service Corridor

CONCEPT DESIGN Proposed North-South Section





CONCEPT DESIGN Entry Plaza